



# Product Discontinuation Notification

Document availability: **Public**

## Title: Discontinuation of uEye XCP Rev.1 cameras with USB3 interface

<b>Affected Product:</b>	IDS uEye cameras (detailed list of models in document) <ul style="list-style-type: none"><li>• Models with match code UI-3xxxXCP (USB3 interface)</li></ul>
<b>Document Version:</b>	1.0
<b>Release date:</b>	August 1 <sup>st</sup> 2024

## Reasons and Description of the Product Discontinuation

IDS is constantly working on updating and improving its products. One enhancement is the standardization of the hardware basis of the uEye XCP, XLE and XLS series camera families. This adjustment fixes a rare GPIO toggling problem that occasionally occurred when starting uEye XCP Rev.1 cameras.

Cameras with no revision information printed on the camera label are referred to as Rev.1 cameras. IDS decided to phase out the USB3 XCP Rev.1 cameras due to the Rev.1.2 camera successor models.

All details about the revision change from Rev.1 to Rev.1.2 can be looked up in the corresponding PCN:

- [PCN 2023-09-18 USB3 XCP Rev.1.2 GPIO.pdf](#)

## Recommended action for customers

IDS suggests to switch to the below listed successor camera models of the uEye XCP Rev.1.2 series. Customers still have the opportunity to place a final order for uEye XCP Rev.1 cameras by the date listed below. For any question regarding last time orders or successor models, please contact our sales team.

## Important Note

The affected discontinued cameras are not supplied with firmware feature updates any more.

## Important Dates

End of Sale	Last Shipment Date	End of Support
28 <sup>th</sup> February 2025	28 <sup>th</sup> March 2025	28 <sup>th</sup> March 2028

## Affected Cameras

Illustrations may differ from the original.



U3-3xxxXCP Rev.1

## Affected Part Numbers and Successors

Besides placing last time buy orders, IDS suggests to switch to the below listed successor

Part number U3-3560XCP Rev.1 discontinued	Part number U3-3560XCP Rev.1.2 successor
AB03214	1008718
AB03215	1008719
AB03216	1008717

Part number U3-3680XCP Rev.1 discontinued	Part number U3-3680XCP Rev.1.2 successor
1007509	1008730
1007515	1008733
AB03079	1008725
AB03080	1008726
AB03254	1008733

Part number U3-38J0XCP Rev.1 discontinued	Part number U3-38J0XCP Rev.1.2 successor
AB03282	1008735
AB03283	1008737
AB03284	1008738

Part number U3-38L0XCP Rev.1 discontinued	Part number U3-38L0XCP Rev.1.2 successor
1008929	1008132