



Product Discontinuation Notification

Document availability: **Public**

Title: Discontinuation of uEye XLE Rev.1.1 cameras

Affected Product:	IDS uEye cameras (detailed list of models in document) <ul style="list-style-type: none">• Models with match code UI-3xxxXLE Rev.1.1 (USB3 interface)
Document Version:	1.0
Release date:	August 1 st 2024

Reasons and Description of the Product Discontinuation

IDS is constantly working on updating and improving its products. One enhancement is the standardization of the hardware basis of the uEye XCP, XLE and XLS series camera families. This adjustment adds GPIO support.

IDS decided to phase out the USB3 XLE Rev.1.1 cameras due to the Rev.1.2 camera successor models.

All details about the revision change from Rev.1.1 to Rev.1.2 can be looked up in the corresponding PCNs:

- [PCN 2023-09-18 USB3 XLE Rev.1.2 GPIO.pdf](#)

Recommended action for customers

Form and fit of Rev.1.2 cameras does not change compared to older revisions.

- No action required when the I/O connector is not used in customer application.
- No action required neither by customer for housed camera versions U3-xxx0XLE or U3-xxx6XLE. The I/O connector is inside the housing and is not accessible.
- The change does affect board level camera models U3-xxx1XLE, U3-xxx2XLE and U3-xxx4XLE.

IDS suggests to switch to the below listed successor camera models of the uEye XLE Rev.1.2 series. Customers still have the opportunity to place a final order for uEye XLE Rev.1.1 cameras by the date listed below. For any question regarding last time orders or successor models, please contact our sales team.

Important Note

The affected discontinued cameras are not supplied with firmware feature updates any more.



Product Discontinuation Notification

Important Dates

End of Sale	Last Shipment Date	End of Support
28 th February 2025	28 th March 2025	28 th March 2028

Affected Cameras

Illustrations may differ from the original.



U3-3xx0XLE Rev.1.1



U3-3xx1XLE Rev.1.1



U3-3xx2XLE Rev.1.1



U3-3xx4XLE Rev.1.1



U3-3xx6XLE Rev.1.1



Product Discontinuation Notification

Affected Part Numbers and Successors

Besides placing last time buy orders, IDS suggests to switch to the below listed successor

Part number U3-356xXLE Rev.1.1 discontinued	Part number U3-356xXLE Rev.1.2 successor
1007525	1008731
1007527	1008732
1007545	1008761
1007547	1008762
1007553	1008763
1007557	1008764
1007603	1008765
1007605	1008766
1007607	1008767
1007535	1008734
1007539	1008736
1007541	1008739



Product Discontinuation Notification

Part number U3-368xLE Rev.1.1 discontinued	Part number U3-368xLE Rev.1.2 successor
1007670	1008744
1007672	1008745
1007673	1008746
1007674	1008747
1007784	1008748
1007699	1008787
1007700	1008788
1007701	1008789
1007702	1008790
1007706	1008791
1007785	1008793
1007691	1008784
1009485	1009412
1007692	1008785
1007786	1008786
1007688	1008780
1007689	1008781
1007690	1008782
1007787	1008783
1007625	1008740
1007626	1008741
1007627	1008742
1007628	1008743



Product Discontinuation Notification

Part number U3-38JxXLE Rev.1.1 discontinued	Part number U3-38JxXLE Rev.1.2 successor
1007268	1008751
1007269	1008753
1007270	1008770
1007271	1008771
1007272	1008773
1007273	1008775
1007274	1008777
1007275	1008778
1007276	1008779
1007277	1008754
1007278	1008756
1007279	1008757